

HABS
DC,
WASH,
395B-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Auditors Complex, Annex Building 2
Corners of Independence Avenue, 15th Street SW
and 14th Street SW
Washington
District of Columbia

HABS No. DC-524-B

Photographer: John Alvord

March 2, 1985

DC-524-B-1 NORTH AND EAST SIDES

DC-524-B-2 WEST END OF NORTH SIDE, ADDITION IN FOREGROUND

DC-524-B-3 EAST FRONT, DETAIL OF CABLE

DC-524-B-4 NORTH SIDE, ROOF AND GABLE END DETAIL

DC-524-B-5 SOUTH SIDE, ROOF DETAIL

DC-524-B-6 SOUTH SIDE, TYPICAL DORMER

DC-524-B-7 FIRST FLOOR INTERIOR, SOUTHWEST CORNER

DC-524-B-8 INTERIOR OF ADDITION, NORTHEAST ROOM LOOKING NORTHWEST

Photocopies of Photographs; taken 1905 by Ambrose B. Stannard, Contactor during
construction of Annex 3

DC-524-B-9 WEST SIDE OF CONSTRUCTION SITE, ANNEX 2 AT RIGHT

DC-524-B-10 VIEW FROM NORTHWEST, ANNEX 2 IN BACKGROUND

DC-524-B-11 VIEW FROM NORTH, ANNEX 2 IN BACKGROUND

DC-542-B-12 VIEW FROM WEST, ANNEX 2 AT RIGHT, MAIN AUDITORS BUILDING AT LEFT

DC-542-B-13 VIEW OF CONSTRUCTION SITE FROM NORTHWEST CORNER OF ANNEX 2, SHOWING
RELATIONSHIP OF SITE TO THE MALL AND THE WASHINGTON MONUMENT